

Neutrarust NR 661 - Instructions

NR 661 is a rust converter that is simply painted onto rust and acts as a high quality primer.

- 1) Remove loose material with a wire brush and ensure no contamination from oil or grease.
- 2) Pour required amount into a paint kettle or suitable container.
- 3) Paint a thin coating of NR661 onto the rusted surface, the white liquid will turn blue.
- 4) Leave to dry, 10 – 20 minutes depending on ambient temperature. Rust will have turned black and NR661 will have dried to a clear finish.
- 5) 60 minutes after initial drying time, apply a second coat to ensure an impervious seal.

THAT'S IT!

Being water-based, Neutrarust adsorbs any surface moisture during its curing process and the strong resin forms a seal. The second coat is recommended to ensure that the seal is complete.

NR661 can be painted over with Neutrarust TL Barrier Coat or most other paint systems.

Note: As NR661 can dry to a high gloss finish, it may be necessary to lightly abrade to provide a 'key' for subsequent paint coatings.